## ASSEMBLY INSTRUCTIONS

(For LD1031C-46\*86)


## ATTENTION:

- 1. Please read these instructions carefully before assembly.
- 2. Aluminum is soft metal over tighten may strip threads or break the part.
- 3. DO NOT use power tools.
- 4. Check parts against the parts list to make sure you have all parts needed for proper assembly.
- 5. Familiarize yourself with the inventory of parts and the accompanying illustrations to ensure safe and proper assembly.

## Assembly steps:

- 1. Turn the table top(A) upside down on the soft clean surface. Loosely attach the legs(C) to the table Top with bolts(D), big flat washers(E), big lock washers(F) nuts(G) and nut caps(H) using the wrench(N). Tighten the bolts at this time.
- 2.Loosely attach the center ring(B) to the legs (C) with small flat washers(J), small lock washers(K), screws(I) and PVC covers(L) using the wrench (M).
- 3. Tighten all the bolts and nuts completely. DO NOT over-tighten.
- 4. Turn the table onto its legs. Use the adjuster feet to level the table.

Warning: DO NOT use acid or alkaline washing liquid to clean the product.



Parts list	Parts picture	Description	Qty		Parts list	Parts picture	Description	Qty
Α		Table top	1		D	((((() (M8*30)	Bolt	4
				-	E	(M8)	Big flat washer	4
Вı	P	Center ring	1		F	(M8)	Big lock washer	4
				-	G	(M8)	Nut	4
B <sub>2</sub>		Center ring	1		Н	Œ	Nut cap	4
					I	(M6*35)	Screw	8
С		Table leg	4		J	(M6)	Small flat washer	8
	/	10.0.0 109			K	(M6)	Small lock washer	8
Q		Foot leveler	4		L		PVC cover	8
0		Umbrella cover	1		М		Wrench	1
					N	5 3	Wrench	1

Made in China

**\*DO NOT OVER TIGHTEN** 

**\*NO POWER TOOLS** 

**\*NO SOCKET DRIVERS** 



